

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number. 67054	
4. Organization Name and Address.		Aerospace Turbine Rotables Inc. 3414 W 29th St South Wichita, KS 67217 US Ph: (316) 943-6100, Fax: (316) 943-2917 FAA Approval Holder: NV2R045L				5. Work Order, Contract or Invoice Number: WO23648	
6. Item	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	FLAP ACTUATOR	50-521222-4	N/A	1.00	314-E-91	OVERHAULED	
13. REMARKS							
<p>Overhauled and certified IAW the documents listed. Full details of work performed held on work order.</p> <p style="text-align: right;">Manual ID: 101-590097-13, Revision #: B6, Revision Date: 11/1/2011</p> <p>The work specified in Block 12/13 was performed in accordance with EASA-Part 145 and with respect to the work, the aircraft component is considered ready for release to service under EASA Approval Certificate.EASA.145.4033</p>							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval Authorization No:		20. Authorized Signature:		21. Approval/Certificate No:	
				<i>William E Briggs</i>		NV2R045L	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed):		23. Date (m/d/y):	
				WILLIAM E. BRIGGS		May/22/2012	
User/Installer Responsibilities							
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.</p> <p>Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.</p> <p>Statement in Blocks 14 and 19 do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>							

JAN 08 2014 PO-13-11415



QA Document

Company:

Address:

Receiver #: R3253

Order #: BEEHCRAFT 1900D - ERICKSON

Entered: 5/18/2022



Part Number	NSN	Qty	Qty Appr	Qty Rej	Cond	Location	Control #	ID	Serial #	Hologram #
Description		Max Qty	Qty Appr Hist	Qty Rej Hist	Consign	Warehouse				
50-521222-4		1.00	1.00	0.00	OH	G-R4-B11				
ACTUATOR, FLAP		0	0.00	0.00	_	WHS1	4596	1	314-E-91	

*Findings for S/N #314-E-91**Findings:*
