

1. Approving National Aviation Authority/Country: FAA/United States	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 316369
--	---	---

4. Organization Name and Address: www.avionics-specialist.com PK4R443M	Avionics Specialist, Inc. 3833 Premier Avenue/Memphis, Tennessee 38118 U.S.A. Phone (901) 362-9700 Fax (901) 794-8276	5. Work Order/Contract/Invoice: R-51561
--	--	--

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity	11. Serial/Batch Number:	12. Status/Work:
A	COLLINS 334C-6A	792-6780-001	N/A	1 each	1782	REPAIRED

13. Remarks: Approval For Return To Service Reference Work Order: 316369 Technician: HELMS, DAVID Date: 08/27/08
 BENCH TESTED UNIT. FOUND UNIT DIRTY AND NOISY. DISASSEMBLED AND INSPECTED. CLEANED, LUBRICATED AND REASSEMBLED UNIT. PERFORMED COMPLETE OPERATIONAL TESTS. UNIT MEETS MANUFACTURER'S SPECIFICATIONS IN ACCORDANCE WITH PUBLICATION# 523-0762690, REVISION 6, 12/13/96. REFURBISHED AS NEEDED. UNIT HAS NO MODS AS PER MOD TAG.

Avionics Specialist, Inc. certifies that the work specified in block 12/13 was carried out in accordance with EASA Part-145 and with respect to that work the aircraft component is considered ready for release to service under EASA Approval Certificate Number: EASA 145 4220.

<p>14. Certifies the items identified above were manufactured in conformity to:</p> <p><input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation</p> <p><input checked="" type="checkbox"/> Non-approved design data specified in Block 13</p>	<p>19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13</p> <p>Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations; part 43 and in respect to that work, the items are approved for return to service.</p>
---	---

15. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Signature: <i>Michael J. Westphal</i>	21. Approval/Certificate No.: PK4R443M
17. Name (Typed or Printed):	18. Date (m/d/y):	22. Name (Typed or Printed): Michael J. Westphal	23. Date (m/d/y): Aug/27/2008

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

<p>Company: Address:</p>	<p>Receiver #: R4953 Order #: BEEHCRAFT 1900D - ERICKSON Entered: 8/23/2022 <i>pe</i></p>
------------------------------	---

Part Number	NSN	Qty	Qty Appr	Qty Rej	Cond	Location	Control #	ID	Serial #	Hologram #
Description		Max Qty	Qty Appr Hist	Qty Rej Hist	Consign	Warehouse				
792-6780-001		1.00	1.00	0.00	RP	C-R3				
MOTOR, AILERON		0	0.00	0.00	_	WHS1	9059	1	Unknown	

Findings for S/N #Unknown

Findings:
