Autl	ving Civil Aviation 10rity/Country UNITED:STATES	AUTHORIZED I FAA Form 8130-3, Al				tr.a.	3. Form Tracking Number: TP2809	·
4. Organization Name and Address: 5499 I		TURBOPOWER, LLC. W 145 th STREET, UNIT 1, MIAM A. APPROVED REPAIR STATION		II, FLORIDA 33054			5. Work Order, Comract/Invoice Number: Work Order No.: 8025543	
6. Item	7. Description:	8. Part Number:	9. Q	uantity:	10. Serial Number:	,	11. Status/Work:	
1 GEARSHAFT		3014410		1	NSN		OVERHAULED	

12. Remarks:

OVERHAULED I.A.W. OVERHAUL MANUAL P/N 3017043 R40 REMOVED FROM ENGINE S/N CP-PS 61558 TOTAL CYCLES = N/ATOTAL CYCLES REMAINING = N/A

Turbonower certifies that the work specified Implock 12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.5106". La certifies the items identified boyo were manufactured in sonformity to: 14a. ☑ 14CFR 43.9 Retugn To service ☑ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 Approved design data and artin a condition for safe operation.

Antiapproved design data speeded in Black 12. and described in Block 12 was accomplished in accordance with Title 14. Code of Federal Regulations part 43 and in respect, to that work, the items are approved for return to service. 14b. Althorized Signature W. Authorized Signature: 13c. Approval/Authorization No.: MAC. Approval/Certificate No.: NE4R385M 13d. Name (Lynn or printed): 14d. Name (Typed or Printed) 13e. Date (dd/mmm/yyyy): 14. Date(dd/mmm/yyyy) LEON LECOUNTE 20/JUL/2020

User/Installer Responsibilities:

Statements in Block 13a and 3a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by

It is important to understand that the oxilience of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the uner/installer performs of in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in

Block I, It is essential that the use all laller unsures that histher already specified in

FAA Form 8130-3 (02-14)

the uner/installer before the alreralt may be flown

Block 1.