


1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 582402	
4. Organization Name and Address: I. J. Walch Co., Inc. 6600 Preston Ave., Livermore, CA 94551 Phone: (925-449-9252) Fax: (925-294-1780)				FAA Repair Station #NC3R705L Website: www.ljwalch.com		5. Work Order/Contract/Invoice Number: 582402
6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. quantity:	11. Serial/Batch Number:	12. Status/Work:
001	RELAY	SM20ACD200A21	N/A	1	N/A	INSPECTED
13. Remarks: UNIT WAS INSPECTED 06/21/2007 AT LJ WALCH CO. BY EMPLOYEE ID# 223. WORK WAS ACCOMPLISHED I.A.W. A.T.A./CMM# SM20ACD200A21 REV# U DATED 03/01/1996. ALL PERMANENT RECORDS ARE ON FILE AT THIS FACILITY THIS UNIT IS APPROVED FOR RETURN TO SERVICE AS OF THIS DATE. TT: TSO: O/C ALL MANDATORY A.D.'S AND S.B.'S HAVE BEEN COMPLIED WITH OR PREVIOUSLY ACCOMPLISHED L J Walch Company Certifies that the work specified in Block 12 and 13 was performed in accordance with EASA Part 145 approval and with respect to that work, the aircraft component is considered ready for release to service under EASA approval number: EASA.145.4637.						
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input checked="" type="checkbox"/> Non-approved design data specified in Block 13.			19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:	20. Authorized Signature: 		21. Approval/Certificate No.: NC3R705L	
17. Name (Typed or Printed):		18. Date (m/d/y):	22. Name (Typed or Printed): DANIEL F TELLES		23. Date (m/d/y): Jun/21/2007	
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.						
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.						
Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



L. J. Walch Co., Inc.

FAA Repair Station # NC3R705L

6600 Preston Ave, Livermore, CA-94551

Phone: (925) 449-9252

Fax: (925) 294-1780

Remit address: P. O. Box 2798 Livermore, CA 94551-2798

Website : www.ljwalch.com

T E A R D O W N R E P O R T

CUSTOMER: EVERGREEN HELICOPTERS, INC	WORK ORDER 582402
CUST# EVHE	PHONE: W/O DATE 05/25/2007
P.O. NO. R-49090	FAX: 1503-434-4212
AIRCRAFT.....	DATE NEEDED 06/15/2007
TYPE NO. POS. INCOMING TSO UNK	SERVICE REQUESTED
UNK UNK UNK OUTGOING TSO O/C	REPAIR
TOTAL TIME	

DATE REMOVED: 12/18/2006

QTY 1 EA	PART# SM20ACD200A21	RELAY
SERIAL N/A		

REASON FOR REMOVAL: CHG SYST OFF LINE AND WILL NOT RESEAT
EVAL FOR REPAIR

FAILURE: CONFIRMED

FINDINGS: HARDWARE MISSING

DESCRIPTION OF WORK ACCOMPLISHED:

UNIT WAS INSPECTED 06/21/2007 AT LJ WALCH CO. BY EMPLOYEE ID# 223.
WORK WAS ACCOMPLISHED I.A.W. A.T.A./CMM# SM20ACD200A21 REV# U DATED 03/01/1996

MAJOR PARTS USED:

COMMENTS:

VISUAL INSP- UNIT DIRTY. INITIAL TEST-UNIT PASSED ALL TESTS.
T/D INSP- AUX TERMINALS NEED TO BE REPLACED (WIRES WERE CUT) SOME MISSING.
MAIN TERMINALS ARE OXIDATED. NO OTHER DEFECTS FOUND.
CLEANED TERMINAL, HARDWARE AND UNIT. DRESSED MAIN CONTACTS. REPLACED
TERMINALS.
UNIT INSPECTED & TESTED IAW MFG SPECS.

MECHANIC: 223

INSPECTOR: DANIEL F TELLES



DATE: 06/21/2007

QA Document

<p>Company: Address:</p>	<p>Receiver #: R4780 Order #: BEEHCRAFT 1900D - ERICKSON Entered: 8/15/2022 <i>PLV</i></p>
------------------------------	--

Part Number	NSN	Qty	Qty Appr	Qty Rej	Cond	Location	Control #	ID	Serial #	Hologram #
Description		Max Qty	Qty Appr Hist	Qty Rej Hist	Consign	Warehouse				
SM20ACD200A21		1.00	1.00	0.00	SV	A-R3-B4				
BREAKER, CIRCUIT		0	0.00	0.00	_	WHS1	8678	1	Unknown	

Findings for S/N #Unknown

Findings:
